



德昌電子(集團)有限公司

TAK CHEONG ELECTRONICS (HOLDINGS) CO.,LTD.

PRODUCT DISCONTINUE NOTIFICATION

PDN No: PDN-08-002

RELEASE DATE:Aug.7-2008

TITLE: Discontinue The Production Of Selected Zener Devices

LAST BUY DATE: Aug.31-2008

LAST SHIP DATE: Dec.31-2008

FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION, PLS.CONTACT WITH,

Name: Engelbert Lo
E-mail: Engelbert.Lo@takcheong.com
Direct Line: 86-660-337 6121

DESCRIPTION AND PURPOSE:

Tak Cheong Electronics is discontinuing the selected zener devices list in the attachment.
The last order acceptance will be on end of Aug.2008 and last delivery date will be latest on end of Dec.2008

If further assistance is needed for these parts,pls contact with your nearest Tak Cheong's sales agent.

AFFECTED PRODUCT LIST: (Details as attachment)

POSSIBLE REPLACEMENT PART: None

.....
Approved By:

Manufacturing Manager: _____

QA Service Manager: _____

Mfg QA Manager: _____

Biz Development Manager: _____

.....



德昌電子(集團)有限公司

TAK CHEONG ELECTRONICS (HOLDINGS) CO.,LTD.

产品中止公告

PDN 编号: PDN-08-002
发布日期: 2008 年 8 月 7 日

主 题: 废止已选定的稳压产品

最后购买日期: 2008年 8月31日

最后发货日期: 2008年12月31日

若您对此通知有任何疑问, 请联系

姓名: 卢维明
邮件: Engelbert.Lo@takcheong.com
直线: 86-660-337 6121

描述与目的:

德昌电子有限公司停止生产已选定的稳压产品如附件, 收单日期将于2008年8月31日截止, 交货日期将于2008年12月31日终止。

对于这些产品, 如还需要我们协助的, 请联系与您最近的德昌代理商进行商谈。

受影响产品清单: 详见附件

可代替的产品: 无

批准人: _____

制造经理: _____

品质保障 经理: _____

制造品控 经理: _____

业务拓展 经理: _____



AFFECTED PRODUCT LIST

受影响的产品清单

Device Name	Package	Device Name	Package	Device Name	Package	Device Name	Package
1N4678	DO-35	MZ4614	DO-35	1N5985B	DO-35	BZX55C2V4	DO-35
1N4679	DO-35	MZ4615	DO-35	1N5986B	DO-35	BZX55C2V7	DO-35
1N4680	DO-35	MZ4616	DO-35	1N5987B	DO-35	BZX55C3V0	DO-35
1N4681	DO-35	MZ4617	DO-35	1N5988B	DO-35	BZX55C3V3	DO-35
1N4682	DO-35	MZ4618	DO-35	1N5989B	DO-35	BZX55C3V6	DO-35
1N4683	DO-35	MZ4619	DO-35	1N5990B	DO-35	BZX55C3V9	DO-35
1N4684	DO-35	MZ4620	DO-35	1N5991B	DO-35	BZX55C4V3	DO-35
1N4691	DO-35	MZ4621	DO-35	1N5992B	DO-35	BZX55C4V7	DO-35
1N4692	DO-35	MZ4622	DO-35	1N5993B	DO-35	BZX55C5V1	DO-35
1N4693	DO-35	MZ4623	DO-35	1N5994B	DO-35	BZX55C5V6	DO-35
1N4694	DO-35	MZ4624	DO-35	1N5995B	DO-35	BZX55C6V2	DO-35
1N4695	DO-35	MZ4625	DO-35	1N5996B	DO-35	BZX55C6V8	DO-35
1N4696	DO-35	MZ4626	DO-35	1N5997B	DO-35	BZX55C7V5	DO-35
1N4697	DO-35	MZ4627	DO-35	1N5998B	DO-35	BZX55C8V2	DO-35
1N4698	DO-35	MZ4099	DO-35	1N5999B	DO-35	BZX55C9V1	DO-35
1N4699	DO-35	MZ4100	DO-35	1N6000B	DO-35	BZX55C10	DO-35
1N4700	DO-35	MZ4101	DO-35	1N6001B	DO-35	BZX55C11	DO-35
1N4701	DO-35	MZ4102	DO-35	1N6002B	DO-35	BZX55C12	DO-35
1N4702	DO-35	MZ4103	DO-35	1N6003B	DO-35	BZX55C13	DO-35
1N4703	DO-35	MZ4104	DO-35	1N6004B	DO-35	BZX55C15	DO-35
1N4704	DO-35	1N4370A	DO-35	1N6005B	DO-35	BZX55C16	DO-35
1N4705	DO-35	1N4371A	DO-35	1N6006B	DO-35	BZX55C18	DO-35
1N4706	DO-35	1N4372A	DO-35	1N6007B	DO-35	BZX55C20	DO-35
1N4707	DO-35	1N746A	DO-35	1N6008B	DO-35	BZX55C22	DO-35
1N4708	DO-35	1N747A	DO-35	1N6009B	DO-35	BZX55C24	DO-35
1N4709	DO-35	1N748A	DO-35	1N6010B	DO-35	BZX55C27	DO-35
1N4710	DO-35	1N749A	DO-35	1N6011B	DO-35	BZX55C30	DO-35
1N4711	DO-35	1N970B	DO-35	1N6012B	DO-35	BZX55C33	DO-35
1N4712	DO-35	1N971B	DO-35	1N6013B	DO-35	BZX55C36	DO-35
1N4713	DO-35	1N972B	DO-35	1N6014B	DO-35	BZX55C39	DO-35
1N4714	DO-35	1N973B	DO-35	1N6015B	DO-35	BZX55C43	DO-35
1N4715	DO-35	1N974B	DO-35	1N6016B	DO-35	BZX55C47	DO-35
1N4716	DO-35	1N975B	DO-35	1N6017B	DO-35	BZX55C51	DO-35
1N4717	DO-35	1N976B	DO-35	1N6018B	DO-35	BZX55C56	DO-35
1N984B	DO-35	1N977B	DO-35	1N6019B	DO-35	BZX55C62	DO-35



AFFECTED PRODUCT LIST

受影响的产品清单

Device Name	Package	Device Name	Package	Device Name	Package	Device Name	Package
1N985B	DO-35	1N978B	DO-35	1N6020B	DO-35	BZX55C68	DO-35
1N986B	DO-35	1N979B	DO-35	1N6021B	DO-35	BZX55C75	DO-35
1N987B	DO-35	1N980B	DO-35	1N6022B	DO-35	BZX55C82	DO-35
1N988B	DO-35	1N981B	DO-35	1N6023B	DO-35	BZX55C91	DO-35
1N989B	DO-35	1N982B	DO-35	1N6024B	DO-35	1N991B	DO-35
1N990B	DO-35	1N983B	DO-35	1N6025B	DO-35	1N992B	DO-35
BZX79C2V4	DO-35	BZX79C6V2	DO-35	BZX79C16	DO-35	BZX79C43	DO-35
BZX79C2V7	DO-35	BZX79C6V8	DO-35	BZX79C18	DO-35	BZX79C47	DO-35
BZX79C3V0	DO-35	BZX79C7V5	DO-35	BZX79C20	DO-35	BZX79C51	DO-35
BZX79C3V3	DO-35	BZX79C8V2	DO-35	BZX79C22	DO-35	BZX79C56	DO-35
BZX79C3V6	DO-35	BZX79C9V1	DO-35	BZX79C24	DO-35	BZX79C62	DO-35
BZX79C3V9	DO-35	BZX79C10	DO-35	BZX79C27	DO-35	BZX79C68	DO-35
BZX79C4V3	DO-35	BZX79C11	DO-35	BZX79C30	DO-35	BZX79C75	DO-35
BZX79C4V7	DO-35	BZX79C12	DO-35	BZX79C33	DO-35	BZX79C82	DO-35
BZX79C5V1	DO-35	BZX79C13	DO-35	BZX79C36	DO-35	BZX79C91	DO-35
BZX79C5V6	DO-35	BZX79C15	DO-35	BZX79C39	DO-35	BZX79C100	DO-35
1N5281B	DO-35	1N4757A	DO-41	1N4760A	DO-41	1N4762A	DO-41
BZX85C51	DO-41	BZX85C68	DO-41	BZX85C82	DO-41		

-----The End-----